Digital Weighing Indicator

CT-2100 User Manual



Contents

Chapter 1. Preface	 3 page
Chapter 2. Specification	 4 page
Chapter 3. Installation	 8 page
Chapter 4. Calibration	 9 page
Chapter 5. Set-Up	 19 page
Chapter 6. F-Function	 22 page
Chapter 7. Interface	 34 page
Chapter 8. Error and Treatment	 42 page
Warrantee	 45 page

Chapter 1. Preface

1. Introduction

This CTI-2000 series Digital Weighing Indicator model is 1/8 din sized and provides powerful performance for industrial weighing system applications.

It features an RS-232 serial port that can be expended up to 4pots, so as to easily connect with other devices and PC.

In case of CTI-2100/2500 model has 3pcs control relay output as a standard and also CTI-2500 model has sub-display window, easy to make weighing automation system.

We trust that you will enjoy the performance of CTI-2000 series digital weighing Indicator.

2. Feature

- 2-1. Isolation from the external noise
- 2-2. Watch-dog function
- 2-3. Display resolution, up to 1/30,000
- 2-4. 2pcs Digital input terminal built in (Zero, Tare/Reset)
- 2-5. DC 12V~24V power supply. (Without Polarity)
- 2-6. Data back-up function
- 2-7. Full Automatic Calibration method
- 2-8. Simulating Calibration Method (without Span weight)
- 2-9. Option : Rs-485 / Rs-232(extra) / 4~20mA output

3. Caution

- 3-1. Weak for the drop damage or physical shock.
- 3-2. Do not install heavy electric noise place.
- 3-3. Do not install the heavy vibrating place.
- 3-4. Avoid from the humidity or rain damage.
- 3-5. Please Turn off the main power, when make connect with other devices.

4. Accessories

4-1. User Manual

5. Inquiries

If you have any kinds of inquiries for this model, please contact with your local distributor ADM Instrument Engineering Website : www.admtech.com.au Email : <u>sales@admtech.com.au</u> Phone: 1300 236 467

Chapter 2. Specification

1. Analogue Input and A/D Conversion

Input Sensitivity	0.3µV ∕Digit
Load Cell Excitation	DC 10V (- 5V ~ + 5V)
Max. Signal Input Voltage	Max.32mV
Temperature Coefficient	[Zero] ±10PPM/°C / [Span] ±10PPM/°C
Input Noise	±0.6µV P.P
Input Impedance	Over 10MΩ
A/D Conversion Method	Sigma-Delta
A/D Resolution(Internal)	520,000 Count(19bit)
A/D Sampling Rate	Max. 200times / Sec
Non-Linearity	0.01% FS
Display Resolution(External)	1/30,000

2. Digital Part

Display	Parts	Specification	
	Main Display	7Segments, 5 Digit RED FND Display Size :12.7mm(H)×7.3mm(W)	
Display	Min. Division	×1, ×2, ×5, ×10, ×20, ×50	
Display	Max. display value Under Zero value	+99,950	
		"-" (Minus display)	
	Sub-Display (Only CTI- 2500)	7Segments, 5 Digit RED FND Display Size :8.0mm(H)×4.0mm(W)	
Status	CTI-2000 model Zero, Stable, TARE, AUTO, PRINT, Hold, RTxD	Green LED Display(3Ø)	
lamp	CTI-2100/2500 model Zero, Stable, Low, High, END, Hold, RTxD		
Кеу	Function keys	Zero / F / Set / Enter (4pcs function keys)	

3. General Part

Power Supply	DC 12~24V / About 200~300mA
Operating Temperature Range	-5°C ~ 40°C
Operating Humidity Range	Under 85% Rh (non-condensing)
External Dimension	100mm(W) x 52mm(H) x 125mm(L)
Net Weight(kg)	About 450g
Gross Weight(kg)	About 600g

4. Option

Option No.1	RS-422
Option No.2	RS-232 (Standard Installation)
Option No.5	4~20mA (Analog Output)
Option No.6	0~10V (Analog Output)

5. Front Panel Display

T-2100					CE
					g
STEADY	ZERO	н	FINISH	HOLD	RTxD

5-1. Weight Display

- Current Weight value will be Display
- In case of CTI-2100 model, display set value, whenever press

5-2. Status Lamp (From Left to Right) - CTI 2000 model

- Steady : Lamp is "ON", when the weight value is stable condition.
- Zero : Lamp is "ON", when the weight value is Zero(including Tare weight)
- Tare : Lamp is "ON", when the TARE function is activated
- Auto : Automatic Print Function is Activated, Lamp is "ON"
- Print : Lamp is "ON", when the print function is activated
- Hold : Lamp is "ON", when the Hold function is activated
- RTxD. : Lamp is "ON", when the Comm. is activated
- 5-3. Status Lamp (From Left to Right) CTI 2100 / 2500 model
 - Steady : Lamp is "ON", when the weight value is stable condition.
 - Zero : Lamp is "ON", when the weight value is Zero(including Tare weight)
 - Low : Lamp is "ON", when the weight value reaches to "Low set value".
 - Hi : Lamp is "ON", when the weight value reaches to "HI set value".
 - END(OK) : Lamp is "ON", when the single weighing Batch is finished.
 - Hold : Lamp is "ON", when the Hold function is activated
 - RTxD(TxD). : Lamp is "ON", when the Comm. is activated


6. Key Pad (Basic Function)

Zero	Make current display value to Zero (within the Range) - F08 function setting check
Function	Set / Reset "TARE" function. - F09 function setting check
Set	CTI-2000 model Part No./ Code / Serial No. / Auto print or Manual Print Mode CTI-2100 / 2500 model Low set value or HI set value check or change.
Enter	Save new set value

7. Hot key function

Zero	 Increasing the set value Exit for the "Set-Cal" condition
Function	 Move the display position Move the "TEST mode" from "SET-CAL" mode
Set	 Increasing the Function No. under Function setting mode Enter to "Function mode" from "SET-CAL" mode
Enter	 Start Calibration mode, under "SET-CAL" mode Press this key during 7sec. → Enter to SET-CAL mode. Save new set value and move next step

8. Rear Panel




- 8-1. Load Cell Terminal : EXC+ ~ SHLD
- 8-2. Earth : F.G of DC 24V IN
- 8-3. Power input : PWR of DC 24V IN (without Polarity / No positive and negative)
- 8-4. Digital input : ICOM, IN1 and IN2 (Function 11 check)
- 8-5. Relay output : OCOM, OUT1 ~ OUT3 (Function 21 check only for MI-830 model)
- 8-6. Option : Analogue Output (4~20mA or 0~10V) —> No. 1 (mA+) RS-232C —> No. 2~4 (RXD, TXD, GND) RS-422 —> No. 5~9 (RX+, RX-, TX+. TX-)

Chapter 3. Installation

1. External Dimension 94mm Î 46mm 52mm 125mm 100mm

2. Panel Cutting Size

2.




Chapter 4. Calibration

1. SPAN Calibration

- Adjust weight balance between "Real weight" on the load cell(Weight Part) and "Displayed weight of Indicator". When you replace LOAD CELL or Indicator, you have to do Calibration process once again

- Applicable model : CTI 2000 series

Prepare at least 10% of Max. capacity of your weighing scale.




Step 1. Enter to the "SET-CAL" mod

Step 2. Digit/Division setting



Step 3. Max. Capacity setting





- Determine the Max. capacity of your scale.

Whenever pressing key, value will be increased, Whenever pressing



you can move to the left digit

※ Move to previous step, press



key to save new set value and move to next step.


key

Remarks

Then, Press

- The Max. capacity cannot be exceed Max. capacity of load cell.
- (Digit/Max. Capacity) value must be less than 1/20,000.

Step 4. Measure/Adjustment optimal Zero balance of Scale






- Press key to measure and adjustment Zero balance of Scale.

※ Before press

key, please make clear on the scale part.



Step 5. Input Prepared Test weight value and load on the Scale.





- After a few seconds (to remove the vibration effect), press

Then, indicator will calculate Span value and move the next step.

Remarks : - Please prepare at least 10% of Max. Capacity.

Step 6. End Calibration and Auto Reset



- Calculated Span value will be displayed and automatically reset and move the normal weight indicating mode.

2. Simulating Calibration (Without Test Weight)

- Applicable model : CTI-2000 series

- This calibration Method will be useful to make calibration more than 10ton capacity setting.

- Guaranteed resolution will be 1/5,000 and if you need higher resolution, please make calibration with Test weight.

1 1. Turn on the power while pressing SET key. then display will show 'TEST' key. Then display will show 'SET.CAL' 2. Press SET Then display will show '-----' 3. Press F key. 4. Press 'SET' 'F' 'ZERO' 'ZERO' 'F' 'ZERO'. in sequence

Step 1. Enter to the "SET-CAL" mode

5. Press ENTER. Then display will show 'd _ 1'

Step 2. Digit/Division setting



Step 3. Max. Capacity of Load cell






- Under this step, input Total sum of each load cell's Max. Capacity. (Not weighing Scale)
- The Max. Capacity of load cell is stated on "Test report" or "Label".

- If you installed 4 load cells, and each load cell's Max. Capacity is 500kg, then you have to input 2,000kg, as a Max. Capacity.



Step 4. Measure/Adjustment optimal Zero balance of Scale






- Press

key to measure and adjustment Zero balance of Scale.

* Before press key, please make clear on the scale part.



Step 5. Input Max. Output rate(mV/V) value of load cell

- Under this step, input Max. Output rate(mV) of load cell.

- If you installed a few pieces of load cells, the connection will be parallel, so the rated output of a few load cells are as same as single load cell's rated output.

- The Output rate is stated on "Test report" or "Label"



- key, you can move to the left digit - Whenever pressing
- Move to previous step, press

key

- Press

key to save new set value and move to next step. ENTER



Step 6. End Calibration and Auto Reset

- Calculated Span value will be displayed and automatically reset and move the normal weight indicating mode.

Chapter 5. Set-Up


1. Set-Up

Set-up means set the F-function and make CTI-2000 series weighing controller will perform more accuracy. (Considering external / internal environmental condition)

2. Enter to Set-up mode

- Applicable model : CTI-2000 series

To make more accuracy performance of Digital Weighing Indicator, through this Function setting.




Turn on the Power + with pressing



key to start "Function Mode".

Step 2. Change Function No.






key, function No. will be increased.

(Increase up to "01-53" and return to "01-01")

Stop increase at the desired function No., press





key one more, back to the "ST.CAL" mode.

Step 3. Change New set value for each Function No.



At the function No. display, input new set value with key and



If you press

key to save new set value.



If you don't press ENTER key, new set value will not be saved.

Step 4. Exit Function Mode.




After save new set value with pressing key, then press





key to Function mode.





21

Chapter 6. F-Function List

1. F-Function List

General Function Setting			
F00	Set-up & Calibration Selection	With and key	
F01	Decimal Point setting	0 / 0.0 / 0.00 / 0.000	
F02	Back up Mode	Normal / Back up	
F03	MOTION BAND Range setting	0~9	
F04	ZERO TRACKING Range setting	0~9	
F05	Auto Zero Range setting	00 ~ 99	
F06	Digital Filter setting	01 ~ 49	
F07	"Zero/Tare" key Operation mode select	0, 1	
F08	"Zero" key operation range selection	0, 1, 2, 3, 4	
F09	"Tare" key operation range selection	0, 1, 2, 3	
F10	"Hold" Mode selection	0, 1, 2	
F11	External input selection	0, 1. 2, 3, 4	
F12	Key pad setting	0, 1, 2, 3, 4	
F13	Code No. setting	0, 1, 2	
F14	Hold Off time setting	00~99	

Relay Output Mode setting (Only for MI-830/850 model)			
F21	Weighing Mode Selection	0, 1, 2, 3, 4, 5	
F22	When use Weighing Mode 1 & 2, Comm. Output delay time	00~99	
F24	Weighing Judge Relay "ON" delay time	00~99	
F25	Weighing Judge Relay "ON" duration time	00~99	

Communication Mode setting		
F30	Parity Bit selection Mode	0, 1, 2
F31	Serial Communication Speed selection	0 ~ 9

F32	DATA Transference Mode selection	0, 1
F33	DATA Transference Method selection	0, 1, 2, 4
F34	Equipment No.(ID No.) Selection	1~99
F35	Data Format	0, 1
F36	BCC selection	0, 1
F37	Data Transference count setting	0~6
F40	Weight Unit selection (Communication)	0: kg, 1: g, 2: ton
F53	Average Value display selection	0 : not use / 1~99 : use
F54	Steady LED Status Lamp Delay time setting	0: Not use, 1: Use
F55	Tension and Compression setting	0: Not use (JP 1 OFF) 1: Use (JP 1 ON)
	Other se	tting
F80	Empty Range setting	XXXXXX
F81	Zero display Range setting	X. X X X X X
F82	Zero Deduction Value setting	XX. XX. XX
F83	Max. Analogue output value setting	XX. XX. XX
F85	Simulating Calibration Standard value	XX. XX. XX
F89	Calibration Span value check	X.XX X.XX. X


2. F-function Details

	Set-up & Calibration Selection						
F00	ST	key : Move to Set-up mode key : Move to Calibration mode					
	Decimal Point Setting						
		0	No Decimal Point				
F01		1	1point under Zero				
FUI	•	2	2point Under Zero				
		3	3point Under Zero				
	-	-	Weight-Back up selection				
F02	•	0	Normal Mode				
		1	Weight Back up Mode				

	Motion Band Range					
F03 5 0~9 This is set "Steady" acceptable range of weighing part. If there is vibration on weighing part, you can set this function reduce the vibration effect on weighing process. 0 : Weak vibration 9 : Strong Vibration						
			Zero Tracking Compensation Range setting			
F04	5	0 ∫ 9	Due to external causes(Temperature, wind, and dust), there are small weight difference, indicator will ignore the weight difference and display Zero. For this compensation function, indicator will estimate the weight difference is over the set range during fixed time period. If there is large weight difference over set range within fixed time period, the "Zero" is breaking and will find new zero point.			

Example) Max. Capacity : 100.00kg, Digit : 0.05kg, F04-03 setting

Zero Tracking Compensation Range : $0.5 \times \text{digit} \times F04$ set value = 0.0025x3 = 0.075kgFixed time period : about 5msec. (Fixed time period will be effected on F06(digital filter) setting)




	Auto Zero Range setting					
F05	00	00 ∫ 99	Within the "Auto Zero" range, weighing part is steady, indicator will display current weight as "Zero" If the weighing part is not "Steady", indicator will display current weight. (Auto Zero Range : ± Set value + weight unit)			

X Using this function, you can get the Zero value without pressing "Zero" key, when there is remained material in the hopper within Auto Zero Range.

Example) Max. Capacity : 10kg, Digit : 0.02kg, F005-30 setting,

Under this setting, Indicator will display "Zero" automatically, when the weight is within ± 0.30kg(Set value + weight unit) and Steady.




			Digital Filter setting					
F06	01 15 ~ 49		A : Frequency Filter setting value (0~3) (0 : about 200Hz/sec, 1 : about 500Hz/sec) B : Buffer Filter setting value (1~9)		If "B" set value is fixed, "A" set value is large, the indicator will response more sensitive.			
		_	Zero /Tare key Operation mode	e selectio	'n			
F07	•	0	Activate when "Steady" condit	ion, only				
F07	-	1	Always activated					
			Zero key Operation Range s	election				
		0	Activated within 2% of Max. C	apacity				
		1	Activated within 5% of Max. C	apacity				
F08		2	Activated within 10% of Max.	Capacity				
	• 3		Activated within 20% of Max.	Activated within 20% of Max. Capacity				
		4	Activated within 100% of Max	Activated within 100% of Max. Capacity				
			Tare key Operation Range s	election				
	0		Activated within 10% of Max. Capacity					
	1		Activated within 20% of Max. Capacity					
F09		2	Activated within 50% of Max. Capacity					
	•	3	Activated within 100% of Max. Capacity					
			- "Hold" Mode selectio	n				
	•	0	Peak Hold : Measure Max. we	eight value	e and hold on display.			
F10		1	Sample Hold : Hold current we	Sample Hold : Hold current weight until "Hold Reset".				
		2	Average Hold : Make Average	e during 5	sec and "Hold Display".			
			External Input Selection – MI	310 mode				
	Set V	alue	Input 1		Input 2			
		0	TARE		TARE RESET			
	•	1	ZERO		TARE/RESET			
F11		2	HOLD		HOLD RESET			


		E	xternal Input Se	lection – CTI 2100) / 2500 model		
	Set	Value	Inp	out 1	Ing	out 2	
		0	R	UN	S	STOP	
		1	RUN	/STOP	TARE / TARE RESET		
F11		2	ZE	RO	TARE / TARE RESET		
	•	3	HC	OLD	HOLD	RESET	
		4	TA	ARE	TARE	RESET	
			Key Pad S	etting – CTI 2000	Model		
	Set Value		ZERO			ENTER	
	•	0	ZERO	TARE/RESET	SET	HOLD/RESET	
F12		1	ZERO	HOLD	SET	HOLD RESET	
		2	ZERO	TARE	SET	TARE RESET	
			Key Pad Sett	ing – CTI 2100 / 2	500 Model		
	Set Value		ZERO			ENTER	
	•	0	Zero	Tare/Reset	SET	Hold/Reset	
540		1	Zero	Hold	SET	Hold Reset	
F12		2	Zero	Tare	SET	Tare Reset	
		3	Zero	Run	SET	Stop	
		4	Zero	Run/Stop	SET	Hold/Reset	
			С	ode No. Setting			
• 0			Fixed Code	Fixed Code			
F13		1	Increase on	Increase one by one, whenever finish the batch			
		2	Decrease o	ne by one, whenev	ver finish the batc	h	
			Hold Off time se	etting (only for F10	0-1/2 setting)		
F14	00	00~9	99 0.0sec ~ 9.9	9sec : Hold function	n will be off		


	Weighing Mode selection								
	•	1	Normal Batch – Limi	Normal Batch – Limit					
		2	Programming Batch	Programming Batch – Packer					
F21		3	Comparison 1. (Che	Comparison 1. (Checker 1)					
		4	Comparison 2. (Che	Comparison 2. (Checker 2)					
		_	Relay output Mode(Ea	ach weighing Mode)					
W	eighing N	lode	Output 3	Output 2	Output 1				
1	Lin	nit	SP1(Low)	SP2(High)	SP3(Empty)				
2	Pac	ker	SP1(Low)	SP2(High)	SP3(Empty)				
3	3 Checker 1 SP1(Under) SP2(Over)		SP2(Over)	SP3(Pass)					
4	Checker 2 SP1(Under) SP2(Over) SP3(Pass)								

■ Relay Output Mode Setting – only for CTI 2100 / 2500 model




♦ Weighing Mode 2. Packer Mode





♦ Weighing Mode 3. Checker Mode 1 – Simple Comparison

♦ Weighing Mode 4. Checker Mode 2 – Simple Comparison



"Co	"Communication Output" delay time(t1) setting (Under F32- 01, F33- 00 setting) when use weighing mode 1, 2 – only for CTI 2100/2500 model					
			After current weight is reached to FINAL, you can set some delay time of "Comm. output			
		00	Steady point			
		00	$SP4 \land \land$			
			SP3 VVV			
F22	10	ſ	FINISH Relay $\leftarrow t1$			
			Com-Out5			
		99				
			"00" setting : At Steady point, Comm. output			
			"20" setting : After 2.0sec from Steady point, Comm. output "99" setting : After 9.9sec from Steady point, Comm. output			
"STE/	ADY" Ji	udging de	lay time(t3) setting (Only for F21-03 : Checker mode 1) – only for CTI 2100/2500 model			
			After current weight is reached to each set point, you can set			
			some delay time of "STEADY".			
		01	Steady point			
		•	SP4/ \\/			
		c	SP3 000			
F24	10	J	t3			
			Com 1, 2,3			
		99				
			"00" setting : At Steady point, FINISH relay output			
			"20" setting : During 2.0sec, hold "Steady" relay "99" setting : During 9.9sec, hold "Steady" relay			
"STE/	ADY" Ji	idging "C	DN" time(t4) setting (Only for F21-03 : Checker mode 1) – only for CTI 2100/2500 model			
			After current weight is reached to each set point, you can set			
			some delay time of "STEADY".			
		00	Steady point			
		r				
F25	10	J	t4			
		a -	Com 1, 2, 3			
		99				
			"00" setting : During the weight reaches to "Empty Range". "20" setting : During 2.0sec, Relay will be on.			
			"99" setting : During 9.9sec, Relay will be on.			

Communication Mode setting

	Parity Bit selection Mode					
	•	0	No Parity			
F30		1	Odd Parity			
		2	Even Parity			
			Serial Communication Speed selection			
		0	115,200bps			
		1	76,800bps			
		2	57,600bps			
		3	38,400bps			
F31		4	28,800bps			
		5	19,200bps			
		6	14,400bps			
	•	7	9,600bps			
		8	4,800bps 2,400bps			
	DATA T	ransfere	nce Mode selection (Under F32-00, F35-00 setting, only)			
F32	•	0	Stream Mode : Weighing Data will be transferred continuously.			
		1	Finish Mode : When Finish Relay output, only 1 time transferred.			
			DATA Transference Method selection			
		0	Simplex Mode / Stream Mode			
F33	٠	1	Duplex Mode / Command Mode			
100		2	LCD Mode			
		4	External Display Mode			
	Γ		Equipment No. setting			
_		01	Equipment No. setting with No. key.			
F34	01	J	(01 ~99 settable)			
		99				
			DATA Transference Format selection			
F35	•	0	Standard Format 1.			
100		1	Standard Format 2			
			BCC Selection Mode			
F 00	•	0	BCC not use			
F36		1	BCC use			

			Data Transference count setting
		0	About 40 times/sec
		1	About 30 times/sec
		2	About 20 times/sec
F37	•	3	About 15 times/sec
		4	About 10 times/sec
		5	About 5 times/sec
		6	About 3 times/sec
	_		Weight Unit selection (Communication)
	٠	0	kg
F40		1	g
		2	ton
			Average Display setting
F53	•	0	Not Use
гоз		1~99	Use (99setting : average display will be a little bit slow)
		St	eady LED Status Lamp Delay time setting
F54	•	0	Not Use
F34		1~99	Delay during 0.1 ~ 9.9sec, and LED lamp will be ON.
			Tension and Compression setting
555	•	0	Not Use (JP1 switch OFF at main board)
F55		1	Use (JP1 switch ON at main board and then must be re- calibration)

Other Setting

		EMPTY Range setting
F80	X.X.X.X.X.X. (0.0.0.0.1.0)	 You can set "EMPTY" Range. Within set range, indicator will not display current weight and just display "Zero". "0.000" setting : When Net Zero, "Zero" status lamp and Near Zero relay will be output. "0.190" setting : Within 190, "Zero" Status lamp and Near Zero relay will be output.
	-	Zero Display Range
F81	X.X.X.X.X.X. (0.0.0.0.1.0)	Zero display range setting If you set 50 as a set value, under 50 weight value will be displayed as Zero. Display will show "0" to "51" directly.
		Zero Deduction Value Setting
F82	X.X.X.X.X.X. (0.0.0.0.1.0)	Display (current weight – set value) on the display panel. If you set 50, current weight is 100, then 50will be displayed.
		Max. Analogue Output Value setting
F83	X.X.X.X.X.X.	At the set weight value, analogue output will be maximized. Ex.) Set 5000, then a weight reached 5000 \rightarrow 20mA or 10V will be output
100	(0.0.0.0.1.0)	But if you need just 3000 of Max. capa, you can input 3000 through this function, then the weight reached 3000 → 20mA or 10V will be output
		But if you need just 3000 of Max. capa, you can input 3000 through this function, then the weight reached
F85		But if you need just 3000 of Max. capa, you can input 3000 through this function, then the weight reached 3000 → 20mA or 10V will be output
	(0.0.0.1.0) X.X.X.X.X.X.X.	But if you need just 3000 of Max. capa, you can input 3000 through this function, then the weight reached 3000 → 20mA or 10V will be output Simulating Calibration Standard Value Check the simulating Calibration standard value. If the value is empty, you can not use Simulating Calibration

Chapter 7. Interface

1. Rs-232C (Standard Installed)

RS-232C Serial Interface is sensitive/weak for electric Noise.

So, please isolate with AC power cable and use shield cable to reduce the electric noise effect.

1-1. Connection



CTI 2000 Series Indicator



4 GND ----- Pin5 GND



PC(D-Sub 9Pin)







Remote Display

CTI 2000 Series Indicator

- 1-2. Signal Format
 - 1) Type : EIA-RS-232C
 - (2) Communication Method : Half-Duplex, Full Duplex, Asynchronous
 - ③ Serial Baud Rate : Selectable
 - (4) Data Bit : 8(No Parity mode, only)Bit.
 - (5) Stop Bit : 1
 - 6 Parity Bit : Non, Even, Odd (Selectable)
 - 7Code : ASCII


1-3. Data Protocol (Data Format 1. – Total 18byte)



- Header 1
 - OL : OVER LOAD or UNDER LOAD
 - ST : Weight Stable
 - US : Weight Unstable
- Header 2
 - NT : Net Weight (Without TARE Weight)
 - GS : Gross Weight (With TARE Weight)
- DATA(8) Symbol(1), Decimal Point(1), Weight (6) = total 8BYTE, like +000.190 - 2B(H): "+"PLUS
 - 2D(H): "-"MINUS
 - 20(H): " "SPACE
 - 2E(H): "."Decimal point
- ► UNIT

- Kg , g

1-4. Data Protocol (Format 2 - Total 22byte)



- Header 1
 - OL : OVER LOAD or UNDER LOAD
 - ST : Weight Stable
 - US : Weight Unstable
- ► Header 2
 - NT : Net Weight (Without TARE Weight)
 - GS : Gross Weight (With TARE Weight)
- ► ID No. : Function 34 setting (Default No is 1)
- ► Lamp : Status Lamp Condition

bit7	bit6	bit5	bit4	bit3	bit2	bit1	bit0
1	Stable	1	Hold	Print	Gross	TARE	Zero

DATA(8) Symbol(1), Decimal Point(1), Weight (6) = total 8BYTE, like +000.190 - 2B(H): "+"PLUS

- 2D(II). T LOS
- 2D(H): "-"MINUS
- 20(H): " "SPACE
- 2E(H): "."Decimal point

► UNIT

- Kg , g

2. Rs-422 Serial Interface (Option)

RS-422/485 serial interface is more stable for electric noise effect compare with other communication method, using electric current difference.

But, install isolated place from Power cable or other electric cables and wires, and please use shielded cable for better performance.

י חעד

Recommendable communication distance is about 1.2km.

2-1. Connection



CTI 2000 Series Indicator

0 KAD+	INDŦ
7 RXD	TXD-
8 TXD+	RXD+





```
PC(D-Sub 9Pin)
```

- 2-2. Signal Format (As Same as "Rs-232C Serial interface)
 - ① Type : EIA-RS-232C
 - (2) Communication Method : Half-Duplex, Full Duplex, Asynchronous

- ③ Serial Baud Rate : Selectable
- (4) Data Bit : 8(No Parity mode, only)Bit.
- (5) Stop Bit : 1
- 6 Parity Bit : Non, Even, Odd (Selectable)


Header2

7Code : ASCII

Header1

2-3. Data Protocol (Data Format 1. - Total 18byte) - As same as "Rs-232c Serial Interface

ID No.



unit

► COMMAN	D MODE MAND [Start(STX 🖸), End(ETX 💟), Succeed(ACK 👥), Fail	
PC→Indicator Format	©01RSNO♥ (ASCII) 02 30 31 52 53 4E 4F 03 (HEX)	
Response from Indicator	CO1RSN0000000 ★● (ASCII) 02 30 31 52 53 4E 4F 30 30 30 30 30 06 03 (HEX)	Serial No.
PC→Indicator Format	€01RCN0♥ (ASCII) 02 30 31 52 43 4E 4F 03 (HEX)	Code No.
Response from Indicator	☎01RCND000058+♥ (ASCII) 02 30 31 52 43 4E 4F 30 30 30 35 38 06 03 (HEX)	
PC→Indicator Format	©01RPNO♥ (ASCII) 02 30 31 52 50 4E 4F 03 (HEX)	Dert N
Response from Indicator	©01RPN019+ (ASCII) 02 30 31 52 50 4E 4F 31 39 06 03 (HEX)	Part No.
PC→Indicator Format	©01RTAR♥ (ASCII) 02 30 31 52 54 41 52 03 (HEX)	TARE weight
Response from Indicator	€01RTAR000758 ★◆ (ASCII) 02 30 31 52 54 41 52 30 30 37 35 38 06 03 (HEX)	value
PC→Indicator Format	©01RCWT♥ (ASCII) 02 30 31 52 43 57 54 03 (HEX)	
Response from Indicator	501RCWTSTNT+00027.6kg ★● (ASCII) 02 30 31 52 43 57 54 53 54 4E 54 2B 30 30 32 37 2E 36 6B 67 06 03 (HEX)	Current Weight value
Remark	STX(1) ID(2) Command(4) Status1(2) Status2(2) Symbol(1) Weight (Include decimal point)(7) Unit(2) ACK(1) ETX(1) = Total 23 BYTE	
PC→Indicator Format	©01RSP1♥ (ASCII) (ASCII) 02 30 31 52 53 50 31 03	Low (SP1)
Response from Indicator	©01RSP1001000 ↔ (ASCII) 02 30 31 52 53 50 31 30 30 31 30 30 30 06 03 (HEX)	DATA

PC→Indicator Format Response from Indicator	³⁰ 01RSP2♥ (ASCII) (ASCII) 02 30 31 52 53 50 32 03 (HEX) (HEX) ³⁰ 01RSP2002000 ♥♥ (ASCII) (HEX) 02 30 31 52 53 50 32 30 30 32 30 30 06 03 (HEX)	High (SP2) DATA		
2. WRITE COM	/IMAND [Start(STX 🖸), End(ETX 💟), Succeed(ACK 舵),	Failed(NAK 🧕)]		
RxD & TxD	Transfer & Response display	Command		
PC→Indicator Format	B01WTAR● (ASCII) 02 30 31 57 54 41 52 03 (HEX)			
Response from Indicator	B01WTAR★♥ (ASCII) 02 30 31 57 54 41 52 06 03 (HEX)	TARE input		
PC→Indicator Format	BO1WTRS♥ (ASCII) 02 30 31 57 54 52 53 03 (HEX)	TARE RESET		
Response from Indicator	02 30 31 57 54 52 53 06 03 (HEX)			
		_		
PC→Indicator Format	©01₩ZER♥ (ASCII) 02 30 31 57 5A 45 52 03 (HEX)	ZERO input		
Response from Indicator	02 30 31 57 5A 45 52 06 03 (HEX)			
PC-→Indicator Format	BO1WSND000058♥ (ASCII) 02 30 31 57 53 4E 4F 30 30 30 30 35 38 03 (HEX)			
Remark	STX(1) ID(2) Command(4) S/N(6) ETX(1)	Serial No. Change		
Response from Indicator	02 30 31 57 53 4E 4F 06 03 (HEX)			
PC→Indicator Format	601WPN019♥ (ASCII) 02 30 31 57 50 4E 4F 31 39 03 (HEX)			
Remark	STX(1) ID(2) Command(4) P/N(2) ETX(1)	Part No. Change		
Response from Indicator	B01WPND★● (ASCII) 02 30 31 57 50 4E 4F 06 03 (HEX)			
PC→Indicator	B01WCND000058♥ (ASCII) 02 30 31 57 43 4E 4F 30 30 30 35 38 03 (HEX)	Code No. Change		
	k = y			

Format		
Remark	STX(1) ID(2) Command(4) Code(6) ETX(1)	
Response from Indicator	CO1WCND ★● (ASCII) 02 30 31 57 43 4E 4F 06 03 (HEX)	

PC→Indicator Format	©01WH0L♥ (ASCII) 02 30 31 57 48 4F 4C 03 (HEX)	
Response from Indicator	CO1WHOL ★● (ASCII) 02 30 31 57 48 4F 4C 06 03 (HEX)	Hold input

PC→Indicator Format	B01WHRS (Ascii) 02 30 31 57 48 52 53 03 (HEX)	
Response from Indicator	B01WHRS★● (ASCII) 02 30 31 57 48 52 53 06 03 (HEX)	Hold RESET

PC→Indicator Format	B01WSTR♥ (ASCII) 02 30 31 57 53 54 52 03 (HEX)	Start(Run) Input
Response from Indicator	B01WSTR ●● (ASCII) 02 30 31 57 53 54 52 06 03 (HEX)	(F21 – 02) (PACK MODE)

PC→Indicator Format	B01WSTD (Ascii) 02 30 31 57 53 54 4F 03 (HEX)	STOP Input
Response from Indicator	B01WSTD ★● (ASCII) 02 30 31 57 53 54 4F 06 03 (HEX)	(F21 – 02) (PACK MODE)

PC→Indicator Format	B01WSP1000200* (Ascil) 02 30 31 57 53 50 31 30 30 32 30 30 03 (HEX)	
Remark	STX(1) ID(2) Command(4) Low <sp1>(6) ETX(1)</sp1>	Low (SP1) set value change
Response from Indicator	B01WSP1++ (ASCII) 02 30 31 57 53 50 31 06 03 (HEX)	value onlange

PC→Indicator Format	©01WSP2000400* (ASCII) 02 30 31 57 53 50 32 30 30 34 30 03 (HEX)	
Remark	STX(1) ID(2) Command(4) High <sp2>(6) ETX(1)</sp2>	High (SP2) set value change
Response from Indicator	CO1WSP2+ (ASCII) 02 30 31 57 53 50 32 06 03 (HEX)	

3. Analogue Output (0~10V / Option)


This Option card converts weight value to Analog Voltage output(0~10V) and transfers to external devices(Recorder, P.L.C), controlled by voltage output.

- 3-1. Specification
 - Output Valtage : 0~10V DC output
 - Accuracy : More than 1/1,000

XAs we convert Digital signal(1/30,000 accuracy) to Analogue, so the accuracy will be lower

than Digital signal

3-2. Circuit Diagram and Pint Connection



%This Voltage output is proportioned on weight calibration and outputs 0~10V.

3-3. Adjustment

This output is adjusted as when the weight is "Zero", output is 0V and When the weight is "Full capacity", output is 10V.

If you need additional adjustment, please adjust with "VR1(Zero)", "VR2(Span) on the Analog Output PCB.

※Remark

This Analog option card converts Displayed weight value(Micro-process data) to analog value on D/A Converter(Digital to Analog converter)

This D/A Converter has Max. 1/4,000 accuracy, so this output is not suitable for high accuracy application, like more than 1/3,000.

For 0~5VDC or 1~5VDC analog output, please inform when you inquiry.

3-4. Output Test

Enter to "TEST" mode and select TEST mode 2(key test).



key input : 4mA or 0V output will be activated from Analogue option Card.



key input : 12mA or 5V output will be activated from Analogue option Card.

key input : 20mA or 10V output will be activated from Analogue option Card.

key input : go to exit for test mode.

4. Analogue Output (4~20mA / Option)


This Option card converts weight value to Analog Voltage output(4~20mA) and transfers to external devices(Recorder, P.L.C), controlled by voltage output.

- 4-1. Specification
 - Output Voltage : 4~20mA output (Max.2~22mA)
 - Accuracy : More than 1/1,000
 - Temperature Coefficient : 0.01%/°C
 - Max. Loading Impedance : Max. 500 Ω

% As we convert Digital signal(1/30,000 accuracy) to Analogue, so the accuracy will be lower

than Digital signal

4-2. Circuit Diagram and Pint Connection



9pin D-sub Female connector



% "LO" terminal is not a "GND", so this "LO" terminal do not be connected with other "GND" terminal on other devices.

%This output is proportioned on weight calibration and outputs 4~20mA.

4-3. Output Adjustment

(1) This output is adjusted as when the weight is "Zero", output is "4mA" and When the weight is "Full capacity", output is "20mA".

(2) If you need additional adjustment, please adjust with "VR1(Zero)", "VR2(Span) on the Analog Output PCB.

※Remark

This Analog option card converts Displayed weight value(Micro-process data) to analog value on D/A Converter(Digital to Analog converter)

This D/A Converter has Max. 1/4,000 accuracy, so this output is not suitable for high accuracy application, like more than 1/3,000.

kev.

Chapter 8. Error and Treatment

1. TEST Mode

- Using several Test modes, you can test indicator performance.

5-1. Enter to TEST mode

Press key during 7sec.

Display will show "TEST", then select each test mode, with pressing



Press key for the certain TEST mode, and enter to that TEST mode.

After checking or test each mode, press key to Exit.



key, then enter to Calibration mode.

TEST Modes Guide

Under TEST display, press

TEST 1	- Check Zero Value with Digital Signal.	
TEST 2	- Key test Mode or Analogue Option Card Test	
TEST 3	- Calibration Mode	
TEST 4	- Display Test Mode.	
TEST 5	- Relay Test Mode.	
TEST 6	- Input Test Mode. key to back to the other TEST Mode.	
TEST 7	- Analogue Value amplification Test.	

%If you installed Analogue Option card, you can test Analogue output test with "TEST 2" mode. (Please check detailed information)

2. Error and Treatment

2-1. Load Cell Installation

Error	Cause	Treatment	Remark
Weight Value is unstable	 Load cell broken Load cell isolation resistance error Weighing part touches other devices or some weight is on the weighing part Summing Board Error 	 Measure input/output resistance of Load cell. Measure Load cell isolation resistance Check attach point with other devices. 	 Input Resistance of "EX+" and "EX- " is about 350Ω~450Ω. Output Resistance of "EX- " and "EX+" is about 350Ω. Isolate Resistance is more than 100Ω
Weight Value is increased regular rate, but not return to "Zero"	1). Load cell Error 2). Load cell connection Error	 Check Load cell connection Measure Load cell Resistance 	
Weight Value is increased to under Zero	Load cell Output wire (SIG+, SIG-) is switched	Make wire correction	
"UN PASS" display	Load cell broken or Indicator connection Error	Load cell Check Load cell connection Check	
	Power was "ON" when some weight is on the load cell?	Remove weight on the Load cell	
"OL" or "UL" display	 Load cell broken or Indicator connection Error Loading over than Max. Capacity 	 Load cell Check Load cell connection Check Remove over loaded weight 	

2-2. Calibration Process

Error	Cause	Treatment
Err 01	When Max.capacity/digit value is over 20.00	Re-input the Max. Capacity, less than 20.00 (Max. Capacity / Digit)
Err 04	Standard weight value is over than Max. Capacity	Re-input Standard weight value with Number keys, under Max. Capacity
Err 05	Standard weight value is less than 10% of Max. Capacity	Re-input Standard weight value with Number keys, more than 10% of Max. Capacity
Err 06	 Amp. Gain is too big Sig+ and Sig- wire connection error Test weight is not loaded 	Check standard weight's weight with set value. If there is difference between set value and real weight, please re-input the value (set value is too small)
Err 07	 Amp. Gain is too small Sig+ and Sig- wire connection error Test weight is not loaded 	Check standard weight's weight with set value. If there is difference between set value and real weight, please re-input the value (set value is too big)
Err 08	Under "F-function" model, set value is "N.A"	Check the correct value and re-input
Err 09	When Y.Y has the value between 3.9 ~ 9.9 at Y.YXXXX as Span value, If standard weight value is less than 10% of Max. Capacity	Change the Max.capacity/digit value (Ex: digit $01 \rightarrow 05$)
Err A	When there is continuous vibration on the weighing part,, indicator can not process calibration any more.	 Find vibration cause and remove Load cell check Load cell cable and connecting condition check

WARRANTEE CETIFICATION

This product has passed "CURIOTEC"s strict quality testing.

If there is a defect of manufacturing or abnormal detection within warrantee period, please contact our Agent or Distributor with this Warrantee certificate.

Then, we will repair or replace free of charge.

WARRANTEE CLAUSE

1. The Warrantee period, we can guarantee, is one(1) year from your purchasing date

2. Warrantee Exception Clause

- Warrantee period is expired.
- Any kinds of Malfunction or defection caused by Modification or Repair without CURIOTEC's permission.
- Any kinds of Malfunction, Defection, or External damage, caused by operator
- Any kinds of Malfunction, Defection, caused by using spare part from Non-Authorized Distributor or Agent.
- Any kinds of Malfunction, Defection, caused by not following Warnings or Cautions mentioned on this manual.
- Any kinds of Malfunction, Defection caused by "Force Majeur", like Fire, Flood.
- Without presentation of this "Warrantee Certification".

3. Other

- Any kinds of "Warrantee Certification" without authorized Stamp is out of validity

•

Manufacturer : CURIOTEC Co.,Ltd.	Product	Digital Weighing Indicator
	Model	CTI 2000/2100/2500
581-1, Yongmi-ri, Gwangtan-myeon, Paju-si, Gyeonggi-do, South Korea	Serial No.	
Tel:+82-31-945-9250		
Fax :+82-31-837-9260		
curiotec@curiotec.com http://www.curiotec.com Made in KOREA	AUTHORIZED STAMP	