
Unimeasure Female Connector

This item is supplied with the Unimeasure draw wire potentiometer when Electrical Connection option "C - Connector with Mating Connector" is selected.

300166 is a Replacement Spare Part.

Suitable for Unimeasure Draw Wires Series: JX-P420, JX-PA, JX-P510

The 300166 Female connector is intended to have a cable connected and to connect with the following Male Electrical Connector, which can be mounted on JX Series Draw wire potentiometer body in the following locations:





Series: 300166

PIN-OUT wiring for the male plug is as follows: (The 300166 female plug should be wired accordingly.)



As viewed on transducer and on cable attachment side of mating connector.

ALIGNMENT KEY +Vin NC +Vout

JX-P510

As viewed on ALIGNMENT transducer and on cable attachment side of mating connector.

JX-PA

